



*Hamilton Southeastern Utilities*

**NOTICE OF VIDEO INSPECTION OF SANITARY LATERALS**

Dear Homeowner:

The sanitary lateral that is connected to your home will be inspected by an HSE representative within the next 30 days. We will be doing a video inspection of the lateral to determine the condition of the sanitary system in the area. We will be looking for leaks, breaks, tree roots, and potential blockages in the sanitary lateral.

Prior to the video inspection we may need to flush the lateral with high pressure water. This will be done by a JETTER unit that will be stationed on the road. The video inspection and lateral flushing will be two separate events. Each will only take approximately 30 minutes and **should not be an inconvenience to you**. Workers will be in your yard for a short period of time. All vehicles will have the SAMCO decals and all workers will have a bright yellow SAMCO shirt and/or vest.

If possible, please expose your cleanout cap and try and make it easily accessible. It is located within 3' of the foundation of your home. Sometimes they are covered by mulch or very thick bushes. It is a small white PVC cap that is 4" or 6" in diameter. We will be using this lateral entry point for our assessment. If it is not exposed we will try and locate it ourselves.

Thank you for your cooperation and if you have questions, please call 317.776.6233. You may also visit [hseutilities.com](http://hseutilities.com) for more information.

Sincerely,

SAMCO  
SANITARY MANAGEMENT & ENGINEERING CO., INC.  
CONTRACTOR FOR HAMILTON SOUTHEASTERN UTILITIES